

KERN & Sohn GmbH

Ziegelei 1 D-72336 Balingen E-Mail: info@kern-sohn.com Tel: +49-[0]7433- 9933-0 Fax: +49-[0]7433-9933-149 Internet: www.kern-sohn.com

Service manual Counting scale

KERN CFS

Version 1.0 5/2011 GB



CFS-SH-e-1110



KERN CFS

Version 1.0 5/2011 Service manual Counting scale

Table of Contents

1		Basic information		
2	Technical data4			
3		Appliance overview		
	3.	1 Keyboard overview6		
	3.	2 Overview of displays7		
4		Menu9		
	4.	1 Navigation in the menu9		
	4.	2 Menu overview10		
5		Adjustment 12		
6		Technical parameters (configuration bulk material balance)		
	6.	1 Technical specifications14		
	6.	2 Menu settings15		
7		Second balance interface 18		
8	Error messages			
9		Troubleshooting		
1(0 Schematics			
11	1 Explosion diagram			

1 Basic information Grundlegende Hinweise

The device must be repaired only by trained specialist staff or personnel with professional formation (such as a repair-specialist accredited by law concerning verification).

The service manual is obligatory for repair work.

After repair, original conditions of the device have to be restored.

Only original spare parts should be used.

Das Gerät darf nur von geschultem oder beruflich ausgebildetem Fachpersonal (z. B. eichrechtlich anerkannter Instandsetzer) repariert werden.

Die Serviceanleitung ist bindend für Reparaturen.

Das Gerät muss nach erfolgter Reparatur wieder in den Originalzustand zurückversetzt werden.

Es dürfen nur Originalersatzteile verwendet werden.

2 Technical data

KERN	CFS	
Weighing Units	kg, lb	
Warm-up time	2 h	
Permissible ambient condition	0° C to 40° C	
Humidity of air	max. 80 % relative (not condensing)	
Weighing plate, stainless steel	294 x 225 mm	
Dimensions of the housing (B x D x H)	320 x 330 x 125 mm	
Mains connection	Mains adapter 230 V AC, 50 Hz; balance 9 V DC, 500 mA	
Rechargeable battery (Option)	Operating duration approx. 70 h / loading time approx. 12 hours	

3 Appliance overview



- 1. Weighing plate / rechargeable battery compartment (under weighing plate)
- 2. Bubble level
- 3. RS 232 interface
- 4. Second balance interface
- 5. Foot screws
- 6. ON/OFF switch
- 7. Mains adapter connection

3.1 Keyboard overview



Choice	Function in Weighing mode	Function in Menu
0 _0 ₩x Yz	Numeric keys	
•	 Decimal point At numeric input number selection to the left 	
	Delete key	
M+	 Addition in summation memory Display total weight /number of weighings / total quantity At numeric input digit selection to the right Data output (menu setting "RU oFF") 	
M	Set or call-up PLU	
PRE	Tolerance control	Call up menu
	Switch-over balance	
REF	 Input of the average piece weight by weighing 	
Numeric input of the average piece weight		Function /parameter selection
	Switch-over weighing unit	
TARE	Taring key	• Confirm
→0←	Zeroing key	Back to menu/weighing mode

3.2 Overview of displays



Display weight

Here the weight of your goods is displayed in [kg].

The arrows $[\mathbf{\nabla}]$ above the symbols show:

NET Net weight	
2	Stability display
→ 0←	Zeroing display
lb/kg	Current weighing unit

Display average piece weight

Here the average reference weight of a sample is displayed in [g]. This value is either numerically entered by user or calculated by weighing on balance.

The arrows $[\mathbf{\nabla}]$ above the symbols show:

.	Number of parts placed on balance too small		
≣ ↑	Piece below minimum weight of piece		
M+	Data in summation memory		
1 <u>5</u> 2	 Active balance: 1. Reference balance KERN CFS 2. Bulk material balance, e.g. KERN KFP 		

Display quantity

Here the current piece quantity (PCS = pieces) or in totalizing mode the sum.

*	Tolerance control in counting mode
Tolerance control in weighing mode	
+	Goods to be weighed above tolerance limit
TOL	Goods to be weighed within tolerance range
-	Goods to be weighed below tolerance limit

The arrows $[\mathbf{\nabla}]$ above the symbols show:

4 Menu

The menu is structured in the following menu blocks.

- 1. FIOFF Balance and application settings
- 2. F2 PrE Settings serial interface
- 3. U ... Setting user identification number
- 4. 5[,] Setting balance identification number
- 5. *EEEH* Configuration balance or balance bridge

4.1 Navigation in the menu

Call up menu	Switch-on balance and during the self test press The first menu block F ↓ oFF is displayed.
Select menu block	⇒ With help of , the individual menu blocks can be selected one after the other.
	FloFF⇔F2Prt⇔Uid⇔SCid⇔EECH⇔FloFF
Select menu item	⇒ Confirm selected menu block with TARE . The first menu item is displayed, e.g. $F \downarrow oFF \Rightarrow bEEP$
	With help of eff, the individual menu items can be selected one after the other.
Select setting	⇒ Confirm selected menu item with setting will be displayed.
Change settings	\Rightarrow Switch into the available settings using \textcircled{FF} .
Acknowledge setting / exit the menu	⇒ Press , balance will return to submenu
	Or make more adjustments in the menu or go back to main menu using.
Return to weighing mode	⇒ Press →0+ anew

4.2 Menu overview

Menu block main menu	Menu item submenu	Disponib adjustme	ole ents	Explanation
FIOFF	ЬЕЕР	"688P""6FF "		Signal tone switched off
		"ЪЕЕР"	" n n "	Signal tone on, if weighing value within tolerance limits
		"ЪЕЕР"	őn oUĽ	Signal tone on, if weighing value outside tolerance limits
	EL	"LI ŁE"	" _o ff"	Display background illumination off
		"LI EE"	" on "	Display background illumination on
		"LI EE"	" <i>RUE</i> "	Background illumination switches on automatically when loaded or a button is pressed
	Unit	"ปกเะ""	רטינא"	Weighing unit can be switched over kg ⇔ lb
		"ปกเะ""	rilo"	Weighing unit "kg"
		"ปกเะ""	۲۵ "	Weighing unit "lb"
	OFF	0/3/5/15/30		Auto-off function, balance will switch off automatically after the set time.
	16 33	66 970	11	Selectable 0/3/5/15/30 minutes.
	866	8[[(00	l otalizing mode on
		866 0	oFF″	Totalizing mode off
F2 PrE	ProdE	Print	RU ₀FF	Data output of stable weighing values after pressing .
			"AU on "	Automatic data output of stable weighing values after unloading the balance
		P Cont		Continuous data output of all weighing data, (totalizing deactivated)
		P SEr	rΕ	Continuous data output only weight value.
	P 68U3	ь 600		Baud rate 600
		Р 150	0	Baud rate 1200
		6 240	0	Baud rate 2400
		ь 480	0	Baud rate 4800
		ь 960	0	Baud rate 9600

	PRriby	8 . 1	8 bits, no parity
		7 E I	7 bits, even parity
		7 0 1	7 bits, odd parity
	РЕУРЕ	EPUP	Standard printer setting
		LPSO	Not documented
5, 0	"U,d"	Shows the current user identification number,	
	"86[234"	max. 6 characters	
			
55 id	"SE 1d"	Shows the current balance identification number,	
	"86[234"	max. 6 characters	
	77 - 1 1		
FECH	Details see chpt. 6	password-protected	

5 Adjustment

- The weight to be used depends on the capacity of the scale. Carry out adjustment as near as possible to the scale's maximum weight. Info about test weights can be found on the Internet at: <u>http://www.kern-sohn.com</u>
 - Observe stable environmental conditions. Stabilization requires a certain warm-up time.

	Operation	Display
₽	Switch-on balance and during the self test press \bigcirc .	"PI N"
₽	Use the number keys to enter password: Either	
	 Standard password "0000" 	"PI N"""
	or	
	 personal password, input see chapter 6.2 	
⇒	Confirm input with .	
⇔	When using as counting system, the bulk material balance as well as the reference balance must be adjusted. The adjustment process must be carried out on both balances.	"EEC H " "LoCRL" ≎
	Select bulk material or reference balance via . The appeared [▼] displays the current balance. Acknowledge with .	"£80 H " "r8No£8"
⇔	If necessary, at balance zero display using UNIT select the weighing unit [kg or lb], which shall be used for adjustment. The appeared [▼] displays the current weighing unit. Acknowledge with TARE.	"EEC H ""UNIE"
\hat{T}	Ensure that there are no objects on the weighing plate. After successful stop check press the button.	"UNLoRd"

Ŷ	The weight value of the required adjustment weight will be displayed. Acknowledge with TARE.	" SEL ""000003"
⇔	Place the required adjusting weight carefully in the centre of the weighing plate and press to	"LoAd"
or	confirm.	
₽	Enter value of the necessary adjustment weight using numeric keyboard and acknowledge with .	"SEL" "000002"
	In order to achieve high-quality weighing results in the sense of the measuring technology, it is recommended to select the nominal value as high as possible. We recommend 80 % max.	
₽	Place the required adjusting weight carefully in the centre of the weighing plate and press to confirm.	"LoAd"
₽	After the adjustment the balance will carry out a self-test. Remove adjusting weight during self test, balance will return into weighing mode automatically. In case of an adjustment error or incorrect adjusting weight the display will show an error message $(FRI \ L \ H \ / \ FRI \ L \ L)$, repeat adjustment process.	

6 Technical parameters (configuration bulk material balance)

 \Rightarrow Changes should only be carried out by trained specialized personnel.

⇒ Navigation in menu see chpt. 4.1

In factory the balance **KERN CFS** or the counting system **KERN CCS** are preconfigured in a way that normally no more changes will be necessary. But if there are special conditions of use or if as bulk material balance another weighing bridge (not preconfigured by **KERN**) is connected, in the menu block "EELH" the required settings can be made.

6.1 Technical specifications

1

Supply voltage	5 VDC	
Max. signal voltage	0-20 mV	
Zeroing range	0-5 mv	
Sensitivity	> 0.02 µv/internal ADC count	
Internal ADC count	500,000 Max. at 10mV input	
Resistance parameter	87 Ω Min., 4 x 350 Ω load cell	
Connector	4 poles	
Max. cable length	6 meter	
Connection plug	9 pin d-subminiature bushing	

6.2 Menu settings

Ca	all up menu	FloFF
分	Switch-on balance and during the self test press \bigcirc	
⇔	Press repeatedly until EECH is displayed.	FECH
	FloFF⇔F2Prt⇔Und⇔SCnd⇔ttlH	
₽	Acknowledge with TARE. The request to enter the password appears.	"PI N"
1	Or as standard password enter four times zero "0000" or the stored password (input see parameter "PI II"). Any other password can be overwritten with "9999".	"PI ∏"""
₽ ₽	Use to select the balance which should be configured (bulk material/reference balance). The appeared [▼] displays the current balance. Acknowledge with TARE.	"EECH""LoCAL" ♀ "EECH""rENoEE"
ᡎ	Use UNIT to select the weighing unit [kg or lb], where the adjustment shall be made. The appeared [▼] displays the current weighing unit. Confirm with the first menu item <i>"Locc"</i> appears.	"EECH" " UNI E" ↓ "[∩E"

Na	vigation in the menu	
⇒	With help of , the individual menu items can be selected one after the other.	
⇔	Confirm selected menu item with TARE. The current setting will be displayed.	
⇔	Switch into the available settings using	
⇔	Or store with $ext{rec}$ or reject with $ext{rec}$.	
Pa	rameter selection	"Ent"
1.	Display internal resolution	
2.	Balance capacity	"C 8 P "
	Settings only possible on the bulk material balance.	Û
⇔	Press Tare, the currently set position of the decimal dot is displayed.	"JESC""0.00 " ₽
	Select the desired setting by $\overset{\text{Ref}}{\checkmark}$ and acknowledge on $\overset{\text{TARE}}{\frown}$. The currently set capacity is displayed.	"SEL " "000 100 "
	For changes delete display using and enter the desired	Û
	value via the numeric keyboard. Confirm input with . The currently set readability is displayed, for changes see step 3 "Readability".	"In[""I"
3.	Readability	"dıu"
		Display at selection reference balance
⇒	Press TARE, the currently set readability is displayed. Select the desired setting by EF and acknowledge on TARE.	₽ "In[""I"

4.	Automatic zero point correction (Autozero) by changing the display, digits selectable (0.5d, 1d, 2d, 4d)	" 825 "
⇒	Press , the currently set value is displayed.	Ţ.
	Press to select the desired setting (0.5d, 1d, 2d, 4d) and	"82n" "Id"
	acknowledge by pressing	
5.	Zero setting range Load range where the display after switching-on the balance is set to zero	"O RUŁo"
⇔	Press , the currently set zero setting range is displayed.	ъ "П ВШБа""П"
	Press $\overset{\text{Ref}}{=}$ to select the desired setting (0 %, 2 %, 5 %, 10 , 20	0 1.000 10
	%) and acknowledge by pressing .	
6.	Zero setting range	""
	Load range where the display is set to zero by pressing $\stackrel{\flat 0 \leftarrow}{\frown}$	υ οθοί
⇔	Press Tare, the currently set auto-zero range is displayed.	₽ "∩ =0-!""2
	Press to select the desired setting (0 %, 2 %, 5 %, 10 %,	
	20 %) and acknowledge by pressing \mathbf{L}^{TARE} .	
7.	Password input for menu block "EECH"	"P, n"
⇔	Press , "Pinl" is displayed. Use the numeric	₽ "Pint"
	keyboard to enter the desired code and acknowledge with $^{\text{TARE}}$.	Û
⇒	"Рип?" is displayed, request to repeat the password input.	" 7 ? "
	Enter code anew and press to acknowledge. At successful	" doof "
	input, ["] doっ E " is displayed, at wrong input ^{" FRI} L ". In this	00000
	case repeat the code input.	

7 Second balance interface

When using as counting system, the weighing bridge must be connected with a suitable cable via the second-balance interface.

9 pin d-subminiature bushing of the balance		Connection of weighing bridge, e.g. KERN KFP	
Pin no.:	Balance connection		
Pin 1 or 2	EXC+ (5V)	see labelling of load cell	
Pin 4 or 5	EXC- (0)		
Pin 7	SIG-		
Pin 8	SIG+		

8 Error messages

Error message	Description	Possible causes	
"Err 4"	Zeroing range exceeded due to switching-on balance	 Object on the weighing plate 	
or pressing $\stackrel{\bullet 0 \leftarrow}{\longrightarrow}$ (normally 4% max)	or pressing ^{↔o₊} (normally 4% max)	Overload when zeroing	
		 Improper adjustment 	
		Damaged weighing cell	
		Damaged electronics	
"Err 5"	Keyboard error	 Improper operation of the balance 	
"Err 6"	Value outside the A/D changer range	 Weighing plate not installed 	
		Damaged weighing cell	
		Damaged electronics	
FRILH / FRILL	Adjustment error	Improper adjustment	

Should other error messages occur, switch balance off and then on again. If the error message remains inform manufacturer.

9 Troubleshooting

A. Unit does not turn on



B. No display indication



C. Can't charge the battery



D. Can't weigh



E. Unstable readout



F. Keyboard without function



Note:

M/B means main board, D/B means display board. CHK means check.





CFS-SH-e-1110

Display









11 Explosion diagram



No	Parts name	Qty	Material	Spec
1	pan	1	SST	230mmx300mm
2	pan	1	ABS	230mmx300mm
3	battery cover	1	ABS	
4	rechargeable battery	1	lead acid	6V/4Ah
5	foam	1	CR	
6	top cover	1	ABS	
7	rear overlay			
8	name plate	1		
9	internal hexagon screw	4		M6x20, 8.8
10	washer (M6)	4	65Mn	200-300HV
11	spring washer (M6)	4		HRC42-50
12	load cell upper bracket	1	Aluminum	
13	load cell	1		
14	hexagon screw	4	20Mn	M4x16
15	hexagon nut	4		M4
16	"+" triangle thread screw	4	20Mn	M4x20
17	load cell lower bracket	1	Aluminum	
18	main PCB	1		
19	bottom cover	1		ABS
20	self thread screw	5	20Mn	4x12
22	foot	4	PVC	
25	front display overlay	1		
26	keyboard	1		
27	level bubble	1		14.7mm
28	screw	1		M4x35
29	front display PCB	1		
30	insulative washer	7	EDPM	8x3.1x1.2t
31	self thread screw	5	S18C	3x12
32	self thread screw	5	S18C	4x8
33	insulative washer	4	EDPM	10x4.2x1.2t
34	"+" self thread screw	2	20Mn	3x10
36	screw for D connector	4		
37	D type connector	2		
38	hexagon nut for D connecto	4		
39	RS-232 overlay	1	PC	
40	power switch	1		